

GFWQ

WALK-AROUND

Control Locks Off
Mags Off & Key Out
Avionics Master Off
Fuel On Both
Master On
Fuel Gauges Check
Lights Check
Flaps Down
Master Off
Loose Articles Stowed
Fire Ext. .. Secure & Charged
First Aid Kit Secure
Aircraft Walkaround

Mixture Lean 1"
Fuel Right Tank
Flaps Up / Moving Together
Audio Panel Set
ELT Check on 121.50
Radios Set
Transponder Sby
Controls Free & Correct
Fuel On Left Tank
Flight Instruments Set
Brakes Check
Radio Check / Airport Advisory
Instruments Turning Check

PRE-START

Belts and Seats Secure
Fuel On Both
Mixture Rich
Throttle Cracked
Carb Heat Cold
Beacon On
Time Note

START

Prop Area Clear
Brakes Set
Prime As Required
Master On
Ignition Switch Start
Throttle 1000 rpm
Oil Pressure Check
Avionics Master On

RUN - UP

Area Clear
Fuel On Both
Mixture Rich
Throttle 1700 rpm
Oil Temp & Press Check
Ammeter Charging
Suction 4.6 - 5.4
Mags Check
Max Drop – 125
Max Diff – 50
Carb Heat On & Check
Mixture Check Operation
Slow idle Check
Carb Heat Cold
Throttle 1000 rpm
Mixture Lean 1"

GFWQ

PRE-TAKEOFF

Fuel Both
Belts and Seats Secure
Doors & Windows Locked
Fuel Sufficient
Oil Temp & Press Green
Primer Locked
Master On
Mags On Both
Breakers In
Lights As Required
Carb Heat Cold
Flaps Set
Trim Set
T/O Brief **Wind/Rwy/Speeds**

RUNWAY

Icing As Required
Lights As Required
Mixture Set

AFTER TAKEOFF

Flaps Up
Lights As Required
Transponder Alt

BEFORE DESCENDING

Carb Heat On
Mixture Rich

PRE-LANDING

Fuel & Oil Check
Primer Locked
Master On
Mags Both
Breakers In
Lights As Required
Carb Heat On
Mixture Rich
Fuel Both
Brakes Check Pressure
Belts and Seats Secure

AFTER LANDING

Flaps Up
Carb Heat Cold
Mixture Lean 1"
Transponder Sby

SHUTDOWN

Throttle 1000 rpm
ELT Check on 121.50
Avionics Master Off
Beacon Off
Live Mag Check
Mixture Idle Cut-Off
Mags Off (key out)
Master Off
Time Note
Controls Locks On
Seat Belts Stow